


CORNER RECORD

Document Number _____

City of _____

County of Placer, California

Brief Legal Description Lot 19, Squaw Valley View Sub. H/Maps/95, O.R.P.C.



sec. 28

CORNER TYPE

T. 16 N Government Corner Control
R. 16 E. Meander Property
 Rancho Other
MD B & M Date of Survey 10-7-04

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Used record dimensions, and Found 1/2 rebar original monuments per H/Maps/95 O.R.P.C, To re-establish the 2 front corners of Lot 19, as shown on the accompanying Plat.

A description of the physical condition of the monument as found and as set or reset:


Set 5/8" Rebar w/ PLASTIC CAP LS. 7429.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Oct. 8th 2004

Signed [Signature] P.L.S. or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed DECEMBER 16 2004

Signed Charles B. Grant P.L.S. or R.C.E. No. LS 6158



Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



BOOK 9 CORNER RECORDS PAGE 36

PLAT OF SURVEY
LOT 19, SQUAW VALLEY VIEW SUBDIVISION, BOOK
H, AT PAGE 95, OFFICIAL RECORDS PLACER
COUNTY CALIFORNIA, POR N. $\frac{1}{2}$ SECTION 28,
TOWNSHIP 16, N., RANGE 16, E., M.D.B.&M
SCALE 1" = 40' DATE OF SURVEY 10/7/2004



- FOUND MONUMENT AS SHOWN HEREON
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- (1) RECORD PER H/SUBS/95, O.R.P.C..
- DIMENSION PT (NOTHING FOUND OR SET)