

# CORNER RECORD


# COUNTY OF PLACER, CALIFORNIA

City of Unincorporated

Document Number 2014-0094

Brief Legal Description SOUTH LINE PARCEL A; 18PM149 AND 29PM63; CHILI HILL ROAD

PLS Job No. 833



S. 11  
T. 12 N  
R. 7 E

### CORNER TYPE

Government Corner     Control  
 Meander                     Property  
 Rancho                         Other  
Date of Survey                    10/10/14

### COORDINATES

(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner ---  Left as found     Found and tagged     Established     Reestablished     Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

Found Railroad spikes in roadway as noted per Book 18 PM Page 149 and Book 29 PM Page 63

Tied railroad spikes to nails set in canal liner, poles and fences as shown on the sketch.

A description of the physical condition of the monument as found and as set or reset:

All railroad spikes in Chili Hill Road have been covered with a 1-1/2" pavement overlay. Markings are illegible.

The two most westerly spikes are within the limits of the sewer trench and will be destroyed due to excavation.

The easterly spike should be safe.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction

in conformance with the Professional Land Surveyors' Act

on October 29, 20 14

Signed Richard A Marino

L.S. or R.C.E. Number 6376



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 20 \_\_\_\_\_

and examined and filed December 16 20 14

Signed Leslie Amberry Title County Surveyor

L.S. or R.C.E. Number 6584



County Surveyor's Comment \_\_\_\_\_

BOOK 17 CORNER RECORDS PAGE 59

