

CORNER RECORD

Document Number 20150001


City of LINCOLN

County of Placer, California

Brief Legal Description LOT 50, VEDERA VILLAGE 13 - PHASE 3, Z MAPS 58

CORNER TYPE

COORDINATES(Optional)



T.12 N.
R.7 E.

Government Corner Control
 Meander Property
 Rancho Other

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NADV88
 Meas. Units: Metric Imperial

Date of Survey AUGUST 21, 2014

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 3/4" IRON PIPES TAGGED "LS 4533" AND 1" BRASS MARKERS STAMPED "LS 4533"
AS SHOWN ON FINAL MAP NO. 2003-224, VERDERA VILLAGE 13 - PHASE 3, Z MAPS 58.

A description of the physical condition of the monument as found and as set or reset: ALL MONUMENTS WERE FOUND
TO BE UNDISTURBED AND LEGIBLE. REESTABLISHED MISSING CORNER WITH
A MAG NAIL AND TAG STAMPED "LS 7375". SET IN CONCRETE FENCE POST FOOTING.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on FEBRUARY 4, 2015.

Signed John E. Klamm (P.L.S.) or R.C.E. No.: 7375



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined
 and filed FEBRUARY 13, 2015.

Signed Leslie Amberry P.L.S. or R.C.E. No.: 6584

Title County Surveyor

County Surveyor's Comment _____



BOOK 17 CORNER RECORDS PAGE 76

