


CORNER RECORD

Document Number 20140113City of CARNELIAN BAY County of PLACER, CaliforniaBrief Legal Description LOT 15, BLOCK 6, CEDAR FLAT SUBDIVISION. H/MAPS/82

CORNER TYPE

COORDINATES (Optional)

Government Corner Control
 Meander Property
 Rancho Other

N. _____
 E. _____
 Zone _____ Datum _____

Date of Survey NOVEMBER 31, 2014

Elev. _____

T.16 N., R.17 E., MDM

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

● FOUND MONUMENTS IN RECORD POSITION AS SHOWN ON PAGE 2

USED NEAREST FOUND MONUMENTS TO REESTABLISH PROPERTY

CORNERS AS SHOWN HEREON.

FOUND MONUMENTS IN GOOD CONDITION EXCEPT AS NOTED.


A description of the physical condition of the monument as found and as set or reset: _____

○ SET MONUMENT AS SHOWN ON PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on DECMEBER 8 2014.

Signed [Signature] L.S. or R.C.E. Number R.C.E. 20257



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined and filed FEBRUARY 21, 2015 20.

Signed [Signature] Title County Surveyor

County Surveyor's Comment : _____



BOOK 17 CORNER RECORDS PAGE 81

NOTES:

BEARINGS AND DISTANCES ARE RECORD PER CEDAR FLATS SUBDIVISION H/MAPS/82

MONUMENT KEYNOTES:

- ① FOUND 1/2" REBAR PER H/MAPS/82
- ② FOUND 3/4" REBAR PER H/MAPS/82
- ③ FOUND 1/2" IRON PIPE NO RECORD
- ④ FOUND GIN SPIKE AND WASHER LS 7429 PER 17/CR/19 LOT 12, BLOCK 6
- ⑤ SET 5/8" REBAR RCE 20257



BOOK 17 CORNER RECORDS PAGE 81

