


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number 20150015
Brief Legal Description TRACT NO. 1012 - ENCLAVE at GRANITE BAY, BOOK "DD" OF MAPS, PAGE 5



SEC.10
T.10N.
R.7E.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey FEBRUARY 26th, 2015

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
DURING INITIAL MONUMENTATION, THE 5/8" REBAR WITH PLASTIC CAP AT THE SOUTHEAST CORNER OF LOT 12 WAS NOT SET, AS SHOWN ON TRACT No. 1012 "ENCLAVE AT GRANITE BAY" (DD M 5) DUE TO CONFLICT WITH EXISTING WOOD FENCE. SEE SKETCH ON PAGE 2.

A description of the physical condition of the monument as found and as set or reset: _____
SET 5/8" REBAR WITH PLASTIC CAP, STAMPED RCE '25281 ON THE SOUTH LINE OF LOT 12, AS A WITNESS TO THE SOUTHEAST CORNER OF LOT 12. THE 5/8" REBAR BEARS S59° 22' 46"E - 0.80 FEET OFFSET TO THE SOUTHEAST CORNER OF LOT 12. SEE SKETCH ON PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on FEBRUARY 26th 2015

Signed Piero P. Ruggeri

L.S. or R.C.E. Number 25281 Expiration Date 12/31/15



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 2015

and examined and filed MARCH 3 2015.

Signed Leslie Amberry Title County Surveyor

L.S. or R.C.E. Number 6584 Expiration Date 12-31-15



County Surveyor's Comment _____

G:\Job2013\135018\Mapping\Corner Record LOT 12.dwg, 2/26/2015 3:33:25 PM, roc_cadd7

BOOK 17 CORNER RECORDS PAGE 84

