


CORNER RECORD

Document Number 20140043

City of _____

County of PLACER, California

Brief Legal Description LOT 56, PLACER CANYON UNIT NO. 1, BOOK O OF MAPS, PAGE 93



CORNER TYPE

S19
T11N
R8E

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 7/1/2014

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAV88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS OF RECORD AT INTX OF MEADOWSIDE COURT AND
LEXINGTON CIRCLE AND AT THE BEGINNING AND END OF CURVES ON
LEXINGTON CIRCLE PER BOOK O MAPS 93.

A description of the physical condition of the monument as found and as set or reset: SET 5/8" REBAR WITH CAP
STAMPED RCE 33407 AT NE AND SW CORNERS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JULY 22, 2014.

Signed [Signature] P.L.S. or R.C.E. Number 33407



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined

and filed July 29, 2014

Signed [Signature] P.L.S. or R.C.E. Number 6584

Title County Surveyor

County Surveyor's Comment _____



BOOK 17 CORNER RECORDS, PAGE 24

