

CORNER RECORD


COUNTY OF PLACER, CALIFORNIA

City of Unincorporated

Document Number 20140029

Brief Legal Description West Quarter Corner Section 35

PLS Job No. 833



S. 35
 T. 12 N
 R. 5 E

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 2/19/14

COORDINATES

(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner --- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
Found 1-1/2" Copperweld in roadway stamped "LS 4412; 1989 as shown on Book 18 RS 140.

Set random tie points as shown on reverse.

A description of the physical condition of the monument as found and as set or reset:

On site visit in early May, 2014 monument was found in place. It was not destroyed by construction activities for reclaimed water line, but may be paved over at completion of construction. Reference points remain.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction
 in conformance with the Professional Land Surveyors' Act
 on May, 22 20 14
 Signed Richard A. Marino
 L.S. or R.C.E. Number 6376



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 ____
 and examined and filed September 25 20 14
 Signed Leslie Amberry Title County Surveyor
 L.S. or R.C.E. Number 6584



County Surveyor's Comment _____

BOOK 17 CORNER RECORDS PAGE 29



LEGEND:

● FD. OR SET AS NOTED

■ QUARTER CORNER

∧ INSTRUMENT STATION

