

CORNER RECORD COUNTY OF PLACER, CALIFORNIA

City of UNINCORPORATED PLACER COUNTY Document Number 20140053

Brief Legal Description PROPERTY CORNER ON COEFIELD ROAD IN THE SOUTH 1/2 OF SEC. 6 T.12N, R.8E., M.D.M. BOOK 33 PARCEL MAPS, PAGE 118

X	S. 6	CORNER TYPE				COORDINATES (Optional)	
	T. 12N	Government Corner <input type="checkbox"/>	Control <input type="checkbox"/>	Property <input checked="" type="checkbox"/>	N. _____		
	R. 8E	Meander <input type="checkbox"/>	Other <input type="checkbox"/>		E. _____		
		Rancho <input type="checkbox"/>			Zone _____ Datum _____		
		Date of Survey <u>JULY 8 2014</u>			Elev. _____		

Corner--- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner: FOUND RR SPIKE STAMPED LS 4922 SET AS PROPERTY CORNER PER BOOK 33 PARCEL MAPS, PAGE 118. CORNER WAS DESTROYED BY NID CONSTRUCTION ACTIVITIES. RE-ESTABLISHED FROM 3 NAILS SET AS REFERENCE POINTS IN THE ROAD PRIOR TO CONSTRUCTION

A description of the physical condition of the monument as found and as set or reset: SET A 1-1/2" BRASS CAP STAMPED N.I.D. P.L.S. 7757

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on 7-16 20 14.

Signed _____

(L.S.) or R.C.E. Number 7757 Expiration Date 12-31-15



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 _____

and examined and filed September 25 20 14.


Signed Leslie Amberry Title County Surveyor

L.S. or R.C.E. Number 6584 Expiration Date 12-31-15




County Surveyor's Comment _____

BOOK 17 CORNER RECORDS PAGE 33



NO SCALE



DUDLEY

038 260 057

038 260 020

SET 1 1/2"
BRASS CAP
NED P.L.S. 7757

20.00 N39 E

COE FIELD ROAD

1503
543 W

19.99
S13 W

038 260 077

□ SET CONCRETE NAIL

BEARINGS SHOWN ARE COMPASS READING ONLY